PAGE: 1

PRINT DATE: 06.12.96

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE

NUMBER: MS-655-B012-X

SUBSYSTEM NAME: E - DOCKING SYSTEM

REVISION:

0

DEC, 1996

PART NAME VENDOR NAME

PART NUMBER VENDOR NUMBER

LRU

: ENERGIA POWER PANEL

MC621-0067-0009

RSC-E

SUYU.468312.001

SAU

: PUSH BUTTON SWITCH

PKZ-4 (AGO.360.212.TU)

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:
PUSH-BUTTON SWITCHES (TWO DOUBLE POLE SWITCHES UNDER A SINGLE COVER CAP.) TWO POLE, MOMENTARY - APDS "OPEN LATCHES" COMMAND.

REFERENCE DESIGNATORS: 38V73A8A3SB4-B3

36V73A8A3S84-84

QUANTITY OF LIKE ITEMS: 2

(TWO)

FUNCTION:

PROVIDE THE "OPEN LATCHES" COMMAND STIMULI TO CLOSE THE APPROPRIATE CONTACTS IN THE DSCU TO IMPLEMENT THE "OPEN LATCHES" FUNCTION. THE "OPEN LATCHES" SIGNAL IS ROUTED BY THE DSCU TO THE LATCH ACTUATION CONTROL UNIT (LACU) WHICH IMPLEMENTS THE OPERATION OF THE THREE CAPTURE LATCHES (M1, M2, AND M3.)

PAGE: 5

PRINT DATE: 11.02.97

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE

NUMBER: M5-688-B012-02

REVISION# 0 FERDEC, 19976

SUBSYSTEM NAME: E - DOCKING SYSTEM

LRU: MC621-0087-0009

ITEM NAME: PUSH BUTTON SWITCH

CRITICALITY OF THIS

FAILURE MODE: 1R3

FAILURE MODE:

FAILS CLOSED (MULTIPLE CONTACTS WITHIN ONE SWITCH,) SHORTS TO GROUND

MISSION PHASE:

00

ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 103 DISCOVERY

104 ATLANTIS

105 ENDEAVOUR

CAUSE:

A) PIECE PART FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E)

PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS DNLY)? NO

REDUNDANCY SCREEN

A) PASS

B) PASS

C) PASS

PASS/FAIL RATIONALE:

A}

B}

C)

METHOD OF FAULT DETECTION:

NONE

MASTER MEAS, LIST NUMBERS:

NONE

CORRECTING ACTION:

AFTER THE SECOND FAILURE. THE CREW WOULD FIRE RCS JETS TO AVOID COLLISION

BETWEEN THE ORBITER AND ISS.

- FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF SWITCH CONTROL CAPABILITY FOR THE APDS "OPEN LATCHES" CIRCUITS.

PRINT DATE: 11.02.97

PAGE: 6

FAILURE MODES EFFECTS ANALYSIS (FMFA) - NON-CIL FAILURE MODE NUMBER: M5-655-8012-02

(B) INTERFACING SUBSYSTEM(S): UNWANTED "OPEN LATCHES" COMMAND TO THE DSCU.

(C) MISSION: FIRST FAILURE - NO EFFECT.

- (D) CREW, VEHICLE, AND ELEMENT(S): NO EFFECT.
- (E) FUNCTIONAL CRITICALITY EFFECTS:
 WORST CASE, SHUTTLE OF PINAL MECHANISM CONTROL: POSSIBLE LOSS OF CREW OR
 VEHICLE AFTER TWO FAILURES.

 1) ONE OF TWO ASSOCIATED "OPEN LATCHES" SWITCHES FAILS CLOSED. ENABLES
 TWO OF THREE PANEL COMMAND SIGNALS. 2) ONE OF TWO "APDS CIRC PROT OFF"
 SWITCHES FAILS CLOSED. THREE CAPTURE LATCHES INADVERTENTLY OPEN DURING
 DYNAMIC CAPTURE OPERATION.

DESIGN CRITICALITY (PRIOR TO OPERATIONAL DOWNGRADE, DESCRIBED IN F): 1R2

(F) RATIONALE FOR CRITICALITY CATEGORY DOWNGRADE: CRITICALITY DOWNGRADED FROM 1R2 TO 1R3 DUE TO ADDITIONAL FAULT TOLERANCE PROVIDED BY WORKAROUNDS ALLOWED PER CR S050107W.

AFTER THE SECOND FAILURE, THE CREW WOULD FIRE RCS JETS TO ENABLE THEREBY CIRCUMVENT THE WORST CASE DESIGN CRITICALITY EFFECT. IF UNABLE TO PERFORM THE WORKAROUND (THIRD FAILURE), POSSIBLE LOSS OF CREWIVEHICLE DUE TO AN INADVERTENT COLLISION BETWEEN THE ORBITER AND ISS.

- TIME FRAME .

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: MINUTES

TIME FROM DETECTION TO COMPLETED CORRECTIVE ACTION: HOURS

TIME REQUIRED TO IMPLEMENT CORRECTIVE ACTION LESS THAN TIME TO EFFECT? YES

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT: CREW WOULD HAVE SUFFICIENT TIME TO FIRE RCS JETS. PAGE: 7

PRINT DATE: 11.02.97

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE NUMBER: M5-655-8012-02

HAZARDS REPORT NUMBER(S): ORBi 4028

HAZARD DESCRIPTION:

UNCONTROLLED/INADVERTENT COLLISION BETWEEN ORBITER AND ISS.

- AFPROVALS -

PRODUCT ASSURANCE ENGR : M. NIKOLAYEVA

DESIGN ENGINEER

: B. VAKULIN